

Manhole Inspection Summary

Manhole # S41G__025MH

Printed On: 5/28/2009

Page 1 of 5

Inspection ☐ Is Incomplete Rating: **3) Fair**

Record Plat: **41G** Node: **025** Status: **Found**

Insp Date: **3/18/09 12:04 PM**

Incomplete Comments

Crew: **REI**
Inspector: **paulfry**
Firm: **ATS**

Location Address: **1401 E PRATT ST**

Cross Street: **S SPRING CT**

Manhole Type: **Junction**

Location: **Roadway**

Ground Conditions: **Dry**

☐ Prev. Rehab

Weather: **Dry**

Subject To Ponding: **Sheeting**

Comments **BROKE AND REPLACED COVER TO COMPLETE INSPECTION (see photos)**

Cover

Shape: **Circular**

Diameter: **30** (in.) Length: **0** (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary**

Condition: **Sound**

Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

Frame

Offset: **4** (in.)

Condition: ☒ Sound ☐ Cracked ☐ Leaks

Chimney / Frame Adjustment

☒ Exists Material: **Brick**

☐ Parged Height: **11** (in.)

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Corbel

Material: **Brick**

☐ Parged

Type: **Concentric/Eccentric**

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Barrel

Material: **Brick**

☐ Parged

Shape: **Circular**

Diameter: **45** (in.) Length: **0** (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☒ **Deteriorated**

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Bench

☒ Exists Material: **Brick**

☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☒ **Debris**

Channel

Material: **Brick**

☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth: **0**

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Steps

Count: **7** Missing: **0** ☒ **Corroded**

Surcharge

☒ **Evidence Of Surcharge** Depth: **4** (ft.) ☐ Active Surcharge Present

Manhole Inspection Summary

Manhole # S41G__025MH


Printed On: 5/28/2009

Page 2 of 5

Location View



TOP VIEW



MISC.



REPLACED BROKEN COVER

MISC.



BROKE COVER TO GAIN ACCESS

Defect 6



EVIDENCE OF SURCHARGE

Defect 5



DEBRIS ON BENCH

Defect 4



DETERIORATION OF BARREL WALL,
INFILTRATION IN BARREL WALL

Defect 3



CORRODED STEPS

Defect 2



FRAME OFFSET

Defect 1



FRAME LEAKS, LOOSE BRICKS IN
CHIMNEY, CHIMNEY INFILTRATION

Manhole Inspection Summary

Manhole # S41G__025MH

Printed On: 5/28/2009

Page 4 of 5

12 in. Circular Gravity Sewer
Pipe Out @ 12 O'Clock

12 O'Clock Outflow



Pipe Height: **12** (in.) Rod and Bar (Angled)
Pipe Material: **Clay** ☐ Pipe Lined
Invert Depth: **11.70** (ft.) Flow Characteristics: **Fast**
Deposits: ☒ None ☐ Mud ☐ Sludge ☐ Debris ☐ Grease
Silt Depth: **0** (in.) Deposits Extent:
Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

☐ Possible Illicit Connection

12 in. Circular Gravity Sewer
Pipe In @ 6 O'Clock

6 O'Clock Inflow



Pipe Height: **12** (in.) Rod and Bar (Angled)
Pipe Material: **Clay** ☐ Pipe Lined
Invert Depth: **11.65** (ft.) Flow Characteristics: **Fast**
Deposits: ☒ None ☐ Mud ☐ Sludge ☐ Debris ☐ Grease
Silt Depth: **0** (in.) Deposits Extent:
Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

☐ Possible Illicit Connection

Manhole Inspection Summary

Manhole # S41G__025MH

Printed On: 5/28/2009

Page 5 of 5

0 in. Circular Gravity Sewer
Pipe In @ 9 OClock

9 O'Clock Inflow



Pipe Height: 0 (in.)
Pipe Material: ☐ Pipe Lined
Invert Depth: 0.00 (ft.) Flow Characteristics:
Deposits: ☐ None ☐ Mud ☐ Sludge ☐ Debris ☐ Grease
Silt Depth: 0 (in.) Deposits Extent:
Infiltration: Pipe Seal Cond:

Drop:	
Angled:	Reading: 0.00 (ft.)
	Inv Depth: 0.00 (ft.)
Drop Condition:	

Connects To: **Stub connection / abandoned**
☐ Possible Illicit Connection